

Message

From: Spurlin, Steve [/O=EXCHANGELABS/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=7AE2616803EE42B9B9F19A2B12FCE89F-SPURLIN, STEVE]
Sent: 6/3/2019 10:21:03 PM
To: leslie.shaver@tetrattech.com
Subject: FW: Colonial Nashville Airport Update 4/19
Attachments: Complete Site L19.jpg; Excavated Area L19.jpg

Here's a couple potential figures. We can talk next week. Thanks

From: Wyatt, John M. <JMWyatt@colpipe.com>
Sent: Monday, June 3, 2019 2:36 PM
To: Spurlin, Steve <Spurlin.Steve@epa.gov>
Subject: RE: Colonial Nashville Airport Update 4/19

Steve,

I have attached the images as requested. Please let me know if there is another view you would like to see.

We are occasionally recovering small amounts of product from behind the seep dams. We are planning to increase our vacuum rates on our drilled wells to determine if we can influence the seeps.

Thanks,

John

From: Spurlin, Steve <Spurlin.Steve@epa.gov>
Sent: Friday, May 31, 2019 12:49 PM
To: Wyatt, John M. <JMWyatt@colpipe.com>
Subject: [External Message] Re: Colonial Nashville Airport Update 4/19

WARNING: This email originated outside of Colonial Pipeline.
DO NOT CLICK links or attachments unless you recognize the sender and know the content is safe.

Hi John

Trying to finish final report. Instead of me paying EPA contractor to produce maps you probably already have I thought I just if you have maps I can incorporate into report as a referenced attachment.

I believe you had provided a figure with O and M plan that depicted whole site layout. Do you have that figure with key?

Also a figure that incorporates approx extent of soil excavation would be useful.

Thanks. How is site work going?

Sent from my iPhone

On Apr 19, 2019, at 2:10 PM, Wyatt, John M. <JMWyatt@colpipe.com> wrote:

Steve,

We continue to recover out of both trenches above the creek. 3 dams have been installed at the seep area to prevent a majority of the product from reaching the creek. However, there are still occasional drops of sheen observed in the creek at the southernmost end of the seep.

Attached is the map updated interceptor trench 5. If you have any questions, let me know.

Thanks,

John M. Wyatt

Environmental Program Manager
Southeast District

Colonial Pipeline Company
4295 Cromwell Rd. #311
Chattanooga, TN 37421
Ph: 423-713-7568
Fax: 770-754-8119

Colonial Pipeline Notice - This e-mail message (including any attachment) contains information that may be confidential, be protected by attorney-client or other privilege, or constitute non-public information. If you are not the intended recipient, please notify the sender by electronic mail or telephone and delete the original message without making any copies. Use, dissemination, distribution, or reproduction of this message by unintended recipients is not authorized and may be unlawful.

<Colonial Nashville Airport 041919.pdf>

Colonial Pipeline Notice - This e-mail message (including any attachment) contains information that may be confidential, be protected by attorney-client or other privilege, or constitute non-public information. If you are not the intended recipient, please notify the sender by electronic mail or telephone and delete the original message without making any copies. Use, dissemination, distribution, or reproduction of this message by unintended recipients is not authorized and may be unlawful.